




PLATFORM ZERO INCIDENTS

SF16-006


SAFETY FLASH: MOVING PARTS

GOOD PRACTICE

- ✔ Do not remove safety guards and other protection or protective facilities
- ✔ Markings around wheelhouse and sound signal during movement
- ✔ Use PPE, like safety glasses, when using electrical equipment
- ✔ Look around and make sure that it is safe to use the anchor winches or crane
- ✔ Communicate with each other when doing maintenance on moving parts (and switch them off so they cannot be put into operation/motion)



Moving parts can cause for entrapment and cuts.
Only temporarily remove protective facilities for maintenance and repair. Communicate this to your colleagues and mark clearly.



BAD PRACTICE

- ✘ Removing safety guards
- ✘ Walking under a suspended load
- ✘ Standing in the snapback zone
- ✘ Being in the back peak during navigation (considering moving steering equipment)

ACTION QUESTIONS:

- What are the moving parts onboard? How are they protected?
- What is the snapback zone and where is it located?
- How do we help each other to pay attention to this? (for example: addressing one another on unsafe behavior)

Disclaimer: The information in this document was drawn up with the highest possible accuracy. However, the Platform Zero Incidents and its participants cannot be held liable in any way for its content. Adopting measures, suggestions, warnings, etc. must therefore always be preceded by weighing up and risk assessment. Spreading this document among third parties is allowed provided that this is done in the original form.

