



PLATFORM ZERO INCIDENTS

SF19-41

SAFETY FLASH: SLIPPING, TRIPPING AND FALLING

GOOD PRACTICE

- ✔ A tidy work area.
- ✔ Ridges, wheelhouse pit and stairs are marked clearly.
- ✔ Wearing safetyshoes and a life jacket.
- ✔ Sufficient lighting in work area.
- ✔ Walkways (including steps) are free from obstacles and marked with anti-slip.
- ✔ Manholes are closed or sufficiently protected or marked.
- ✔ Walk backwards down the stairs and hold the railing.
- ✔ Ensure a good and safe stepover.



Slipping, tripping and falling is in the inland shipping industry very common, it happens multiple times a week.
Small adjustment can prevent nasty injuries from happening or even worse!



BAD PRACTICE

- ✘ Walking on slippery, wet or icy surface.
- ✘ Wearing inappropriate footwear.
- ✘ Walking backward on deck.
- ✘ Climbing over the pipes.
- ✘ Open manholes without protection or marking.

ACTION QUESTIONS:

- Are ridges, stairs and wheelhouse pit clearly marked on board?
- Which type of footwear do you use on board and when do you use them?
- How do we help each other? (for example; addressing one another on unsafe behavior)

Disclaimer: The information in this document was drawn up with the highest possible accuracy. However, the Platform Zero Incidents and its participants cannot be held liable in any way for its content. Adopting measures, suggestions, warnings, etc. must therefore always be preceded by weighing up and risk assessment. Spreading this document among third parties is allowed provided that this is done in the original form.

